FUEL SUPPLY SYSTEM ACCESSORIES

Tomco Deepseize® Fuel Line Fittings

for Quadrajet, Monojet and Holley Carburetors

Repair Carburetors with Stripped Threads



Save their cost many times over compared to the price of a new carburetor.

These expanding "O" ring fittings repair leaks at the fuel inlet caused by stripped or damaged threads in the carburetor casting. Complete illustrated step-by-step instructions are packaged with each fitting.



FOR 7/8" CASTING INLET

3/8" gas lines -

Part No. 466.

Part No. 470 shorty

5/16* gas lines -

Part No. 467

Part No. 469 shorty

Note: Use shortles for Holley and Rochester Monojet only, DO NOT USE for Rochester 2 bore or Quadrajet 4 bore.

FOR 1" CASTING INLET

Part No. 471 for late model Quadrajet and Dualjet with 3/8" gas line.

Self-Tapping Fuel Line Fittings for GM Carbs

Fix Stripped Threads in Seconds!

No. 406-407 491 Short

No. 416-492 Long



Save the carburetor by repairing it. Take out the original fitting at the gas inlet and replace it with a TOMCO fitting. Made of tough steel, this self-tapping fitting will reach deeper into the body casting, cut and engage new threads. Quick and easy to install.

For 7/8" Casting Inlet. . .

instructions are included with each valve.

Part No. 406 fits 3/8" gas line Short Filter Part No. 407 fits 5/16" gas line Short Filter Part No. 416 fits 3/8" gas line Long Filter



FOR 1" CASTING INLET... No. 491 (Short paper element) No. 492 (Long paper element)

Deepseize® Carburetor Inlet Valve

Repairs Stripped Threads in Dualjet and Quadrajet Carburetors

Saves the expense of a new 2 barrel Dualiet or 4 barrel strip out in the bowl casting. TOMCO Deepseize fuel line fittings. Complete installation

Quadrajet carburetor when the fuel inlet valve's threads Seals with the same time-proven "O" ring principle as the

